

# Pipeline NN Emergency Replacement

BOARD MEETING – GM Comments

---

July 22, 2025



## Background

- Main Break in the early hours Wed. June 11, 2025
- 16" Fusible PVC Installed in 2011
- Catastrophic Failure – under investigation as to root cause



## Background

- North of HWY 76 near Via Montellano



## Background

- Damage was assessed via pipe camera
- Split in pipe extends at least 72 feet under Hwy 76



# Background

- Assessment indicated No damage to the pipeline south of 76 based



